

Download 2006 Porsche Cayenne Repair Manual

cayenne turbo oil consumption - Is it normal for a 2006 cayenne turbo to consume 1 quart of synthetic oil (0/w40) every 2,500 miles. I find that every mont...2010-2012 Cayenne S & turbo models (V8 engines, 4.8 DFI): The camshaft bolt shearing problem affects 2010-2012 Cayenne V8 models (S & turbo). The bolt in question is an aluminum/steel core version, and Porsche's recommended update is all steel. There are a few jobs on the Porsche Cayenne that require removal of the intake manifold for access to items below, such as the starter or the thermostat. Idea 718. The new Cayman is the sequel that continues the 718 era. At their heart, a four-cylinder turbocharged boxer engine beats with the same fighting spirit that delivered countless podium finishes.